

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

V.A. AKSYUK 34-5  
Tip-Tilt Piston Actuator  
Eugene J. Rosenthal (732) 949-1857

1/4




FIG. 1

2/4




FIG. 2

V.A. AKSYUK 34-5  
Tip-Tilt Piston Actuator  
Eugene J. Rosenthal (732) 949-1857

3/4






FIG. 3


4/4



*FIG. 4*



*FIG. 5*



*FIG. 6*